09/821453 Nº609 P. 28/32

PCT/FR00/02254

WO 01/10547

1 / 5




FIG-1




FIG-2

Received at: 3:30AM, 3/29/2001

29. MAR. 2001 10:27

OBLON ET AL (703) 413-3000 DOCKET #2054/00/SOPCT/SHEET 2 OF 5 GOBAIN 0148346696


09/821453 Nº609

P. 29/32

WO 01/10547

2 / 5

PCT/FR00/02254



-18 -12

FIG-3

FIG-4

Received at: 3:30AM, 3729/2001

OBLON ET AL (703) 413-3000

DOCKET #2054/005/07 SHEET 30F 5

09/821453 Nº 6098

WO 01/10547

3 / 5

PCT/FR00/02254





FIG.5



F1G-6

29. MAK. 2001 10:28

OBLON ET AL (703) 413-3000

DOCKET #20540USOPCT SHEET 4 OF 5

DRAIN 0148346696


09/821453


Nº609 P. 31/32

WO 01/10547

/ 5

PCT/FR00/02254





Received at: 3:30AM, 3/29/2001 :29. MAK. 2001 10:28 OBLON ET AL (703) 413-3000 DOCKET #_205_49WSWCT_SHEET_50F_5

SUBAIN 0148346696

09/821453 Nº 609 21 453 P. 32/32

PCT/FR00/02254

WO 01/10547

5 / 5

Batting (110) Battlng(10) Loose FIII (110) Loose FIII (10) 25 20 9 30 5 35 S